

**Flood Control Project Maintenance
Levee Inspections****LMA District Cover Sheet****Spring 2012 Levee Inspection Results****Reclamation District No. 2092 Dos Rios**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Reclamation District No. 2092 Dos Rios

Waterway			Bank	Unit Miles
Unit No. 01 San Joaquin River			Right	3.76
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/17/2012 - 5/17/2012			
DWR Inspector	Pavel Kazi			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location * + Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End	
1			Earthen Levee	Operations & Maintenance Manuals	LS Ma	Inspector Comments: The ownership of this LMA has recently changed and I have contacted them regarding the information. They have not responded to me with all the required information.	°	°	24
DWR ID: DWR_RD2092_01_s_2012_24									
2			Earthen Levee	Emergency Supplies & Equipment	LS Ma	Inspector Comments: According to my last visit with Mr. Lyons Jr, they appeared to have adequate flood fighting materials at their location.	°	°	26
DWR ID: DWR_RD2092_01_s_2012_26									
3			Earthen Levee	Operations & Maintenance Manuals	LS Ma	Inspector Comments: I have sent the new owner a website link to retrieve the necessary O&M manuals for their districts.	°	°	29
DWR ID: DWR_RD2092_01_s_2012_29									
4	0.38	0.70	Earthen Levee	Encroachments	WS Ma	AD : Agricultural Ditch	37.601304 ° -121.164659 °	37.598233 ° -121.167937 °	4
DWR ID: DWR_RD2092_01_s_2012_4									
5	0.51	0.51	Earthen Levee	Animal Control	LS Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.600651 ° -121.166749 °	37.600651 ° -121.166749 °	2
DWR ID: DWR_RD2092_01_s_2012_2									
6	0.55	0.55	Earthen Levee	Animal Control	LS Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.600104 ° -121.166909 °	37.600104 ° -121.166909 °	1 Y
DWR ID: DWR_RD2092_01_s_2012_1									
7	0.55	0.55	Earthen Levee	Animal Control	LS Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.600095 ° -121.166909 °	37.600095 ° -121.166909 °	3
DWR ID: DWR_RD2092_01_s_2012_3									
8	0.77	1.33	Earthen Levee	Encroachments	LS Ma	AD : Agricultural Ditch	37.597291 ° -121.168496 °	37.590568 ° -121.164028 °	968 Y
DWR ID: DWR_RD2092_01_s_2012_968									
9	0.88	0.88	Earthen Levee	Animal Control	LS Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.595762 ° -121.168187 °	37.595762 ° -121.168187 °	6 Y
DWR ID: DWR_RD2092_01_s_2012_6									
10	1.34	1.57	Earthen Levee	Encroachments	LS Ma	AD : Agricultural Ditch	37.590479 ° -121.163844 °	37.587758 ° -121.162349 °	7 Y
DWR ID: DWR_RD2092_01_s_2012_7									
11	1.34	1.34	Earthen Levee	Encroachments	LS Ma	PI : Pipe Inspector Comments: A sand boil appeared on the landside toe of the levee because of an underground pipe leakage.	37.590467 ° -121.163822 °	37.590467 ° -121.163822 °	10 Y
DWR ID: DWR_RD2092_01_s_2012_10									
12	1.34	1.34	Earthen Levee	Animal Control	LS Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.590458 ° -121.163798 °	37.590458 ° -121.163798 °	9
DWR ID: DWR_RD2092_01_s_2012_9									
13	1.36	1.36	Earthen Levee	Slope Stability	LS Ma	S1 : Repair slope instability.	37.590341 ° -121.163549 °	37.590341 ° -121.163549 °	11 Y
DWR ID: DWR_RD2092_01_s_2012_11									
14	1.47	1.47	Earthen Levee	Animal Control	LS Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.589053 ° -121.162168 °	37.589053 ° -121.162168 °	13 Y
DWR ID: DWR_RD2092_01_s_2012_13									

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River				Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
15	1.47	1.47	Earthen Levee	Slope Stability	LS	M Ma	S1 : Repair slope instability.	37.589061 ° -121.162168 °	37.589061 ° -121.162168 °	25 Y
DWR ID: DWR_RD2092_01_s_2012_25										
16	1.53	1.53	Earthen Levee	Animal Control	LS	M Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.588375 ° -121.162084 °	37.588375 ° -121.162084 °	12 Y
DWR ID: DWR_RD2092_01_s_2012_12										
17	1.58	1.58	Earthen Levee	Animal Control	LS	A Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.587657 ° -121.162393 °	37.587657 ° -121.162393 °	23 Y
DWR ID: DWR_RD2092_01_s_2012_23										
18	1.59	1.87	Earthen Levee	Encroachments	WS	M En	AD : Agricultural Ditch	37.587575 ° -121.162454 °	37.584057 ° -121.162387 °	8 Y
DWR ID: DWR_RD2092_01_s_2012_8										
19	1.59	1.62	Earthen Levee	Animal Control	LS	C Ma	A2 : Repair the levee slope damaged by livestock and prevent large animal access. Inspector Comments: New land owner at this levee mile.	37.587564 ° -121.162459 °	37.587117 ° -121.162732 °	970
DWR ID: DWR_RD2092_01_s_2012_970										
20	1.80	2.57	Earthen Levee	Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	37.584737 ° -121.163246 °	37.578584 ° -121.157006 °	20
DWR ID: DWR_RD2092_01_s_2012_20										
21	1.98	1.98	Earthen Levee	Animal Control	LS	C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.584397 ° -121.160363 °	37.584397 ° -121.160363 °	15
DWR ID: DWR_RD2092_01_s_2012_15										
22	2.02	2.02	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M Ma	C2 : Regrade the crown roadway for proper drainage.	37.584355 ° -121.159676 °	37.584355 ° -121.159676 °	27 Y
DWR ID: DWR_RD2092_01_s_2012_27										
23	2.07	2.07	Earthen Levee	Animal Control	LS	M Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.584295 ° -121.158809 °	37.584295 ° -121.158809 °	971 Y
DWR ID: DWR_RD2092_01_s_2012_971										
24	2.09	2.09	Earthen Levee	Animal Control	LS	A Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.584226 ° -121.158437 °	37.584226 ° -121.158437 °	22 Y
DWR ID: DWR_RD2092_01_s_2012_22										
25	2.10	2.10	Earthen Levee	Animal Control	LS	C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.584200 ° -121.158298 °	37.584200 ° -121.158298 °	16
DWR ID: DWR_RD2092_01_s_2012_16										
26	2.13	2.13	Earthen Levee	Animal Control	LS	C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.584004 ° -121.157831 °	37.584004 ° -121.157831 °	17
DWR ID: DWR_RD2092_01_s_2012_17										
27	2.41	2.41	Earthen Levee	Animal Control	CR	M Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.580856 ° -121.156444 °	37.580856 ° -121.156444 °	21 Y
DWR ID: DWR_RD2092_01_s_2012_21										
28	2.41	2.41	Earthen Levee	Animal Control	LS	M Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.580851 ° -121.156438 °	37.580851 ° -121.156438 °	28 Y
DWR ID: DWR_RD2092_01_s_2012_28										
29	2.42	2.42	Earthen Levee	Animal Control	LS	M Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.580441 ° -121.156758 °	37.580441 ° -121.156758 °	14 Y
DWR ID: DWR_RD2092_01_s_2012_14										

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River						Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location *	Rating ** +	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
30	2.67	2.67	Earthen Levee	Slope Stability	LS	M Ma	S1 : Repair slope instability.	37.577214 ° -121.157151 °	37.577214 ° -121.157151 °	19 Y
DWR ID: DWR_RD2092_01_s_2012_19										
31	2.73	2.73	Earthen Levee	Slope Stability	LS	M Ma	S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.	37.576336 ° -121.157217 °	37.576336 ° -121.157217 °	30 Y
DWR ID: DWR_RD2092_01_s_2012_30										
32	2.76	2.76	Earthen Levee	Slope Stability	WS	M Ma	S1 : Repair slope instability.	37.575946 ° -121.157230 °	37.575946 ° -121.157230 °	33 Y
DWR ID: DWR_RD2092_01_s_2012_33										
33	2.84	3.09	Earthen Levee	Encroachments	LS	M En	FE : Fences Inspector Comments: Barbed wire fence on landward slope.	37.574973 ° -121.156647 °	37.574001 ° -121.152183 °	972 Y
DWR ID: DWR_RD2092_01_s_2012_972										
34	3.40	3.40	Earthen Levee	Animal Control	LS A/W	A/W Ma	A2 : Repair the levee slope damaged by livestock and prevent large animal access.	37.573334 ° -121.147022 °	37.573334 ° -121.147022 °	18
DWR ID: DWR_RD2092_01_s_2012_18										

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	6
Start Levee Mile	0.55
End Levee Mile	0.55
Location	Land Side
Category	Earthen Levee
Item	Animal Control

The rodent holes were repaired by the LMA on the landside of the levee looking upstream.

pkazi_s_20120518_060.jpg



Levee Mile Report Line	8
Start Levee Mile	0.77
End Levee Mile	1.33
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of agricultural ditch at the landward toe looking upstream.

pkazi_s_20120305_755.jpg



Levee Mile Report Line	9
Start Levee Mile	0.88
End Levee Mile	0.88
Location	Land Side
Category	Earthen Levee
Item	Animal Control

A rodent hole was found on the landside of the levee looking downstream.

pkazi_s_20120518_061.jpg



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	10
Start Levee Mile	1.34
End Levee Mile	1.57
Location	Land Side
Category	Earthen Levee
Item	Encroachments

An agricultural ditch was found on the toe of the landside of the levee looking upstream.

pkazi_s_20120305_738.jpg



Levee Mile Report Line	11
Start Levee Mile	1.34
End Levee Mile	1.34
Location	Land Side
Category	Earthen Levee
Item	Encroachments

A sand boil was found on the landside of the levee. It was caused by a pipe leak couple of feet below the boil location. LMA was notified to repair it as soon as possible. The picture was taken from the crown looking upstream.

pkazi_s_20120305_740.jpg



Levee Mile Report Line	11
Start Levee Mile	1.34
End Levee Mile	1.34
Location	Land Side
Category	Earthen Levee
Item	Encroachments

During spring inspection 2012, the sand boil was not active but materials were present on the landside toe of the levee. The sand boil occurred due to an underground irrigation pipe leakage. The picture was taken from the crown looking toward the toe of the levee.

pkazi_s_20120518_062.jpg



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	13
Start Levee Mile	1.36
End Levee Mile	1.36
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Slope instability was found on the landside slope of the levee looking upstream.

pkazi_s_20120305_741.jpg



Levee Mile Report Line	14
Start Levee Mile	1.47
End Levee Mile	1.47
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Animal holes were found on the landside of the levee looking upstream.

pkazi_s_20120518_063.jpg



Levee Mile Report Line	15
Start Levee Mile	1.47
End Levee Mile	1.47
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Slope instability was found on the landside of the levee looking upstream.

pkazi_s_20120305_748.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	16
Start Levee Mile	1.53
End Levee Mile	1.53
Location	Land Side
Category	Earthen Levee
Item	Animal Control
Rodent holes were found on the landside of the levee looking upstream.	
pkazi_s_20120305_742.jpg	



Levee Mile Report Line	16
Start Levee Mile	1.53
End Levee Mile	1.53
Location	Land Side
Category	Earthen Levee
Item	Animal Control
Rodent holes were found on the landside slope of the levee looking upstream.	
pkazi_s_20120518_064.jpg	



Levee Mile Report Line	17
Start Levee Mile	1.58
End Levee Mile	1.58
Location	Land Side
Category	Earthen Levee
Item	Animal Control
Rodent holes were repaired by the LMA on the landside slope of the levee looking upstream.	
pkazi_s_20120518_067.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	18
Start Levee Mile	1.59
End Levee Mile	1.87
Location	Water Side
Category	Earthen Levee
Item	Encroachments

View of an agricultural ditch at the waterward toe of the slope.

pkazi_s_20120305_739.jpg



Levee Mile Report Line	22
Start Levee Mile	2.02
End Levee Mile	2.02
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting

Crown depression was found due to vehicular traffic. The picture was taken from crown looking downstream.

pkazi_s_20120305_749.jpg



Levee Mile Report Line	23
Start Levee Mile	2.07
End Levee Mile	2.07
Location	Land Side
Category	Earthen Levee
Item	Animal Control

View of rodent holes in the landward shoulder looking upstream.

pkazi_s_20120305_759.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	24
Start Levee Mile	2.09
End Levee Mile	2.09
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Rodent holes were repaired by the LMA on the landside slope of the levee looking upstream.

pkazi_s_20120518_066.jpg



Levee Mile Report Line	27
Start Levee Mile	2.41
End Levee Mile	2.41
Location	Crown
Category	Earthen Levee
Item	Animal Control

A rodent hole was found on the crown of the levee looking downstream.

pkazi_s_20120518_065.jpg



Levee Mile Report Line	28
Start Levee Mile	2.41
End Levee Mile	2.41
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Rodent holes were found on the landside slope of the levee. The picture was taken from the crown looking upstream.

pkazi_s_20120305_750.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	28
Start Levee Mile	2.41
End Levee Mile	2.41
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Updated picture of rodent hole on the landside of the levee looking upstream during fall 2011 inspection.

pkazi_s_20120305_751.jpg



Levee Mile Report Line	29
Start Levee Mile	2.42
End Levee Mile	2.42
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Rodent holes were found on the landside slope of the levee looking upstream.

pkazi_s_20120305_743.jpg



Levee Mile Report Line	30
Start Levee Mile	2.67
End Levee Mile	2.67
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Slope instability was found on the landside slope of the levee. The slope was also damaged by a vehicle. The picture was taken from the crown looking upstream.

pkazi_s_20120305_747.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	31
Start Levee Mile	2.73
End Levee Mile	2.73
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Slope instability was found on the landside of the levee looking upstream.

pkazi_s_20120305_752.jpg



Levee Mile Report Line	31
Start Levee Mile	2.73
End Levee Mile	2.73
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Updates picture of the slope instability on the landside of the levee looking upstream.

pkazi_s_20120305_753.jpg



Levee Mile Report Line	32
Start Levee Mile	2.76
End Levee Mile	2.76
Location	Water Side
Category	Earthen Levee
Item	Slope Stability

Slope instability was found on the waterside of the levee looking upstream.

pkazi_s_20120305_754.jpg



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 2092 Dos Rios

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	3.76	05/17/2012 05/17/2012	Pavel Kazi

Levee Mile Report Line	33
Start Levee Mile	2.84
End Levee Mile	3.09
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of barbed wire fence along the waterward slope looking upstream.

pkazi_s_20120305_760.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement